Narrabri Gas Project CCC Information Request Response

Reference:	19.3
Request:	What is the cause of the slump at the Tintsfield Pond
Response:	In early September 2016, Santos reported to EPA that repair work would be undertaken when weather permitted to a part of the pond wall at Tintsfield Pond 2 at our Wilga Park property. Minor erosion was identified in one corner of the pond as a result of recent rain. The pond was not in use and empty at the time (other than a small amount of rain water). Repairs to the anchor trench were carried out in early October and there was no effect on the integrity of the pond liner.
	EPA were informed throughout the process.
Briefing Officer:	Todd Dunn Appraisal Operations Manager Narrabri Gas Project
Date:	5 October 2016