

REF	Action	Entity/Person
14.5	Position of new piezo bore at Leewood to be advised to members	Santos

Assigned Bore I.D.	UTM Coordinates (MGA94)		Ground Surface Elevation	Top of Casing Elevation	Total Depth Drilled	Screen Interval*
	<i>Easting</i>	<i>Northing</i>	<i>(mAHD)</i>	<i>(mAHD)</i>	<i>(mBGL)</i>	<i>(mBGL)</i>
LP0BH01S	751441.11	6623826.7	246.06	246.91	10.25	7-10
LP0BH02S	751645.65	6623790.7	245.35	246.24	10.25	7-10
LP0BH03S	751643.37	6623420.8	246.09	247.02	10.25	7-10
LP0BH04S	751603.86	6623006.7	246.71	247.61	10.25	7-10
LP0BH05S	751369.5	6622774.3	247.57	248.44	10.25	7-10
LP0BH06S	751243.63	6623046	247.81	248.7	10.25	7-10
LP0BH07S	751339.31	6623556.5	247.04	247.94	10.25	7-10